This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES.
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.




Figure 1.




Figure 2.




Figure 3.




Figure 4.

GARLE.




Figure 5.




Figure 6.




Figure 7.

8867 **-**

--- - - .

.- - - -

- -

.

•




Figure 8.




Figure 9.




Figure 10.




Figure 11.




Figure 12.





Figure 13.

-.:



Deposition Conditions

Temperature Power Pressure

120 °C 500 W 7.8 mTorr

Figure 14a.




Figure 14b.




Figure 15.




Figure 16.




Figure 17.




Figure 18a.




Figure 18b.

2.5

BNSOR. Mass Spectrometry Center

Ordinal Flavoria: chopagarimocanis/desitrosabito19902.ms
This File 8 1 : CANOYAGETAISCENTERDATAFONASHIO13ACO2.MS
Commant. Lis control

900

9

Figure 19a.




Figure 19b.




Figure 20.




Figure 21.




Figure 22.